

## **SSM 51749**

### **2022 F-150 - Navigation And Sirius Inoperative After SYNC (APIM) Programming Or Replacement**

Some 2022 F-150 vehicles may exhibit inoperative navigation and Sirius XM radio after the APIM was replaced or received a software update. This is the result of the APIM being configured incorrectly. To correct this condition, download and run the APIM Programmable Module Installation application using the Ford Diagnosis and Repair System (FDRS). For claiming, use causal part 14G670 and applicable labor times in Section 10 of the Service Labor Time Standards (SLTS) Manual.